


SECTION

P & M DUE TO TORSION & ECCENTRIC LOAD



WIND LOAD, WEAK-AXIS BENDING

RAM ELEMENTS QUESTION