

Is there an element that can stop the milling at this point?
-EOP element did not work
-Milling Limit element with milling depth set to zero did not work
-Median Line with median type set to zero prevented the right side from drawing

