


## LARS Bridge CONNECT Edition V10 Update 2 Release Notes



### Description

LARS Bridge CONNECT Edition V10 Update 2 is a maintenance release with several modifications and bug fixes as described below.

The following maintenance items are included in this release:

- LARS Connector compatibility with AASHTOWare BrR version 6.8
- Added legends to steel and prestressed concrete reports to explain symbols.
- Several bug fixes

#### Modifications and Bug fixes:

- Corrected occasional problem that occurred in ASD for setting a flag indicating steel beam top flange is continuously braced.
- Corrected capacity calculation problem with member defects included on steel beams.
- Corrected LFD reporting problem when run as LRFD rating method.
- Revised LARS Connector and LARS Export for compatibility with new AASHTOWare BrR version 6.8.